



Designer: Crosby Associates

Implementation: Image Resource Group

**Image Resource Group Scope of Work:**

- Engineering
- Technical Survey
- Product Development
- Prototyping / Samples
- Signage Fabrication
- Building Fascia Refurbishment
- Signage Installation
- Transportation and Logistics
- Jurisdictional Research
- Permit Procurement
- Project Management

Image Resource Group was responsible for the fabrication and installation of all primary and secondary exterior signage applications at the campus of Mutual of Omaha's corporate headquarters. Prior to the installation of any new lettersets, Image Resource coordinated and managed the replacement of bronze anodized (extruded aluminum) shadow-form fascia material at four separate facilities.



**Crosby Associates**